

HOW TO CALIBRATE TANACOM500-1000 MODELS

Wednesday, March 8, 2023

9:46 AM

1. HOLD Reset & Inv Cntr button for 10 sec
2. Press the MODE button and cycle through until correct measurement you'd like to adjust is selected (similar to MP3000)
3. Use LEVER to adjust the measurement that matches with the line amount on your reel.
4. HOLD MODE button down until a long audible beep is heard.
5. Press the RESET button to exit the menu.